5/42

DART AEROSPACE LTD	Work Order:	24400
Description: Bushing	Part Number:	D2617-3
Dwg: D2617 Rev. D1 D2	Qty:	5051
de 05.10.03 M 65.10.03		Page 1 of 1

Step	Location	Procedure	By	Date	Qty
1	DC	Issue Traveler	M	05,10,04	
2	MC	Machine as per Folio FA437 and Dwg D2617 Material: 6061-T6 (QQ-A-225/8 or QQ-A-200/8 or WW-T-700/6) Ø0.375" tubing x 0.058" wall (M6061T6T0.375W.058) Identify as D2617-3  Batch:	Tal	oshob (	51
3	QC2	Inspect parts as they come off the CNC machine	Di L		31
4	QC8	Second check	J.L	0/10/26	57
5	GA	Deburr break all unmarked sharp edges 0.005 to 0.010	١ ٨	05/10/31	51
6	FP	Acid Etch and Alodine as per QSI 005 4.1	510	05/11/19	59
7	QC5	Inspect work to Step 8 3	C.L	oslulay	51
8	ST	Identify and Stock	/	08/11/24	5)
9	AC		500	-,.,,	51
10	DC	Close W/O Inspect Level 21		05/11/25	51

Rev	Date	Change	Revised By	Approved
D	98.04.16	Re-Format	KB	
Е	99.08.23	Re-format, added notes and inspection level	EC	
F	01.01.03	Re-format, made in-house	EC	2/1
G	04.07.14	Reformat; added step 5	KJ/JLM (	lust.

RELEASED

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES						
DATE STEP		PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector	
				٠			,	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B		Varification	Ammayal	Annroyal	
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector	
				•					
		· .							
	<u> </u>								

Part No:	PAR #:	Fault Category: N	ICR:	Yes No DQA:	Date: 08/11/25
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

DART AEROSPACE LTD	Work Order:	24400	
Description: Bushing	Part Number:	D2617-3	
Inspection Dwg: D2617 Rev: D4D2		Page 1 of 1	

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.857	+0.000/-0.010	್ಪಳಿತ್ತಾ				
0.369	+0.004/-0.005	0.369				
· · · · · · · · · · · · · · · · · · ·	,					
		7-2-1				
			,			
						J.,,,,
						· · · · · · · · · · · · · · · · · · ·
		100				
,						· · · · · · · · · · · · · · · · · · ·
*						
				-		
	· .		,,,			

Measured by:	Inl	Audited by:		Prototype Approval:	N/A
Date:	ostiolale	Date: 05(1617	<u>_</u>	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	04.08.09	New Issue	KJ/JLM (	

RELEASED




ADD 02617-7


04.09.10 # 10



DESIG	BW	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHEC	KED #	APPROVED.	DRAWING NO. REV. D D2617 SHEET 1 OF 1
DATE			TITLE SCALE
 01.0	07.04		BUSHING 1:1
 Α		96.10.08	NEW ISSUE
В		97.05.08	.875 WAS 1.125
С		97.06.04	0.369 DIA WAS 0.375
D		01.07.04	ADD MAT'L SPEC AND TOL./DIM. NOTE

CORRECT TOLERANCE (NCR 779) D2617 - 10.058 WALL





## NOTES:

- 1) MATERIAL: 5052-H32 (QQ-A-225/7 OR WW-T-700/4)
  - OR 6061-T6 (QQ-A-225/8, QQ-A-200/8, OR WW-T-700/6)
- BREAK ALL SHARP EDGES 0.005 TO 0.010
- 3) FINISH: ACID ETCH, ALODINE PER QSI 005 4.1
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- ALL DIMENSIONS ARE IN INCHES

Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

## Job Costing Report

Dart Aerospace Ltd. Hawkesbury

Oct 03, 2005 11:23 am

Work Order No : 0024400

Project Name : D2617-3 Project For : WK542

Work Order Type : Main

Main WO Number :

House Part Number : D2617-3 Description : Bushing

Manufactured : Yes

Amount Req'd: 50
Amount Done: 0
Start Date: 10-03-05

Est Finish Date : 10-20-05

Act Finish Date : Drawings Reqd : No

Approval Rec'd :

Ok for Approval :

\$0 Posted to Finished Goods

Department Code:
Burden Flags : NNNNNNN
WO Status : Open
Invoice State : Not Invoiced
Invoice Date :
Invoice Number :
Invoice Amount : 0.00

Order Entry No : OE Value : 0.00

Est Mark Up : 0.000% Actual Mark Up : 0.000%

Estimated Actual Var. % Posted To Post \_\_\_\_\_

Actual Labour Hrs/Amount Done : 0.00
Profits/(Loss) : 0.00 0.00